

MINISTRY OF DEFENCE

Military Aircraft Accident Summaries

2/91 21 January, 1991

MILITARY AIRCRAFT ACCIDENT SUMMARY

AIRCRAFT ACCIDENT TO ROYAL AIR FORCE

PHANTOM XV402

Date:

30 April 1990

Parent Airfield:

RAF Wattisham

Place of Accident:

RAF Valley

Crew:

Two

Casualties:

1 Minor

CIRCUMSTANCES

- 1. On 30 April 90, a Phantom FGR2 returned to RAF Valley, where it was temporarily based, as part of a 4 aircraft formation. Before landing, the Pilot briefed his Navigator that he intended landing firmly due to the lack of headwind, the length of runway available and the relatively high ambient temperature of 22°C (all factors which would increase the landing roll-out distance). The subsequent landing was firm, although not excessively heavy, but the port mainwheel tyre burst immediately upon touchdown.
- 2. The tyre came off the rim and the wheel began to gouge into the runway, wearing itself away in the process. A few seconds later orange flames were seen coming from the port side of the aircraft and extending for some 20 or 30 feet behind. The Pilot and Navigator were unaware that a tyre had burst until Air Traffic Control informed them.

The Navigator saw, in his mirrors, that the port underside of the

aircraft was engulfed in flames and, hearing Air Traffic Control's call of

"On Fire", he informed the Pilot and ejected. Meanwhile, the Pilot decided

to stay with the aircraft and he was able to maintain directional control

without difficulty.

The aircraft came to a halt at the intersection of runways 32 and 19,

close to firecrew who had previously deployed for an earlier, unconnected

incident. The fire was extinguished almost immediately. The aircraft had

sustained damage to the left main leg, wing, flap and aileron and the left

under-wing fuel tank and wing tank were punctured. There was a gouge, near

the threshold of the runway, several metres long and superficial damage

along the length of the ground roll of the aircraft.

CAUSE

The accident was caused by the deflation of the left main tyre, and

subsequent break up of the left mainwheel, shortly after touchdown.

cause of the tyre deflation could not be positively determined, but the

tyre burst its sidewall almost immediately after landing, probably due to

an undetectable flaw in the tyre.

SUBSEQUENT ACTIONS

The aircraft is currently awaiting repair, although this may be

reviewed in light of the future of the Phantom fleet.

Issued by: Public Relations

(Royal Air Force) Ministry of Defence

Main Building

Whitehall

London SW1A 2HB

2.